Licensees Compliance Assessment Report - Aggregate Resources Act									
Background Information Year:									
Licensee: St. Marys Cement Inc. (Canada)			Licenc	e ID#: 624984 Codrington Pit	MNR District/Area Office: Peterborough		gh 		
ot: Pt. Lots 32-34 Conc.: 6 Geographic Twp.: Murray			Municipality: Mun. of Brighton			of Brighton			
Observations									
OPERATING STANDARDS	IN C	No N	NCE? COMMENTS			Remedial Action?			
A - Site Access	100	1,40							
A1 Boundaries (clearly marked)		de	Fencing completed at boundary of West Parcel with east and south boundary demarcated as fence installation is offset from boundary to preserve tree line. Wood stakes at corners of East Parcel and remnants of old fence at boundary.						
A2 Entrance and Exits (location/closed)		ac Po G	Off-site entrance for aggregate haulage at County Road 30 is gated. Farm access at Conc. 5 & 6 Road Allowance (Ferguson Hill Rd.) is also gated. Permanent entrance to West Parcel for aggregate haulage has been gated. Gates to be installed at accesses between West and East Parcels when accesses are established. No activity at East Parcel at this time.						
A3 Lease/Ownership/Extraction Agreement		O	Owner	rship					
B - Site Protection	, , , , , , , , , , , , , , , , , , , ,		, , , , , , , , , , , , , , , , , , , ,						
B4 Fencing	See A1. Fencing at south and east boundary of West Parcel is off-set from boundary to interior of pit except where fence will connect with proposed go point of access between West and East Parcel.								
B5 Fencing (site plan variation or temporary relief granted)	Fencing (site plan variation or temporary relief granted) Fencing of East Parcel to occur prior to extractive of the state of the stat				active operations.				
B6 Screening (trees/berms)	✓	ex	Berm constructed at southwest corner of West Parcel as required prior to extraction in Phase 1. Final shaping, tree planting and hydroseeding has been completed.			prior to ng has b ee n			
B7 Setbacks (15m / 30m or other)	1	S	Setbacks are in place.						
C - Operational Details									
C8 Operating Sequence Sm				Small excavation ongoing in Phase 1, West Parcel.					
C9 Stripping (overburden)	✓		Overburden stripped from two agricultural fields in Phase 1 used for berm construction at southwest corner of West Parcel.			or berm			
C10 Overburden Seeded	1		Overburden placed in acoustic berm which has been vegetated and hydro- seeded.			nd hydro-			
C11 Extraction Depth	✓		Extraction (at max. depth) is permitted to +/- 155 m (asi). Lowest floor elevation +/- 189 m			<u>+/- 189</u> m			
C12 Buildings/Scales (location)	✓	N	None proposed. Scales, scalehouse / office are off-site at Road 30 entrance.			entrance.			
C13 Equipment (any specific conditions or restrictions)	√	0	One loader in use for loading trucks.						
C14 Plant (location/any specific conditions or restrictions)	✓	S	Screening plant on-site and located in approved area.						
C15 Scrap (location/removal)	✓	Se	Scrap is removed on an ongoing basis.						
C16 Stockpiles (location)	√	Si	Stockpiles in extraction area at Phase 1.						
C17 Topsoil (location/seeded)	✓		Topsoil stripped from agricultural fields used in berm. Phase 1 wooded area topsoil to be used for reforestation as a part of early restoration effort (see D34).						
C18 Excavation Faces	✓	М	Multi-lift excavation ongoing in extraction area as per C8.						
C19 Ponds (location/depth)		V	Seasonal natural pond in non-extraction area at West Parcel.			cel.			
C20 Internal Roads (any specific conditions or restrictions)	✓	In	Internal roads for site preparation and haulage of material off-site.						
C21 Haul Routes (external/any specific conditions or restrictions)	1	ea	Off-site aggregate haulage is via north boundary of West Parcel, across hydro easement and through licensee owned lands including adjacent Archer Pit to County Road 30. Signs advising of public road haul route at 2 locations.						
C22 Blast Monitoring Report (quarries only)		 	✓ .						
C23 Dust Suppression	✓	Su	Suppressant to be used as necessary.						
C24 Hours of Operation (any specific conditions or restrictions)	✓	0)	Operational activities are in accordance (Mon. to Fri. / 7 am to 7 pm).			n).			
C25 Well Monitoring Reports	√			Groundwater level monitoring / repo	orting is carried out.				
C26 Identification Sign (as per Sect. 5.22 of Provincial Standards)	~	Pa 5	Signs installed at three locations: i) County Road 30 off-site entrance; ii) West Parcel entrance at hydro line; iii) Ferguson Hill Road farm field access at Conc. 5 & 6 Road Allowance (West Parcel). Signs will be installed at accesses between East and West Parcel (when established).						
C27 Orderly Conditions	1								
C28 Blasting Hours (quarries only)		~	√						

OPERATING STANDARDS	IN COMPLIANCE?			COMMENTS			
		Yes No					
D – Rehabilitation	h,		 	h.,			Y
D29 Disturbed Hectarage	✓		Curren	t year - # of hectares	0.0	Total # of hectares	
D30 Progressive rehabilitation	√		Curren	year - # of hectares	0.0	Total # of hectares	
D31 Sloping of Faces	✓		Not re	quired at this time.			
D32 Grades/Contours/Elevations	✓		Not required at this time.				
D33 Importation of Material (inert)	✓		No importation of fill for rehabilitation purposes.				
D34 Vegetation	✓		Former agricultural lands at the northwest part of the West Parcel (non- extraction area) have been planted with conifer nursery tree stock.				
D35 Final Rehabilitation	1		Not required at this time.				
E - Prescribed Conditions (For Licences issued after	June 27	, 1997))				L
E36 Other Monitoring Reports	✓		Noise Monitoring Program as per Environmental Noise Monitoring Program & Complaint Procedure (Aercoustics, Feb. 24/13): No monitoring required at this time. Monitoring to be undertaken within one (1) month of each time extraction moves into a new area, within each operational phase (as per ARA site plan).				
E37 Requirements of C of A's	✓			Portable crushing and screening equipment has operated this year in 'below grade' locations.			
E38 Noise Mitigation	✓			Noise mitigation berm has been constructed.			
E39 Fuel Storage Tanks	✓			No fuel storage on-site at this time.			
E40 Spills Plan	✓			Corporate plan is in effect.			
E41 Permit to Take Water	✓		Not required.				
E42 Dust Suppression Measures Req'd. (Haul routes, equip, etc.)	✓	<u> </u>	Suppressants used as required.				
F - Other Conditions (As indicated on either Site Plan or Lice	nce)						
F43 Tonnage Condition	✓		650, 000 tonnes per annum (including up to 50,000 tonnes of material that may be imported for blending purposes).				
F44 Community Liaison Group (CLG)	✓		Public meeting held on April 10, 2014 in Codrington to organise CLG. Subsequent correspondence with interested community members has occurred. Most recent CLG meeting held on May 12, 2015.				
F45 Alternate 'back-up' warning devices	✓		CBM has investigated alternative warning devices for use on CBM-owned equipment. Documentation of same has been provided to Municipality.				
F46 Complaint Response Procedure (Noise)	✓		No noise complaints received to date. Documentation by CBM to include Noise Complaint Form as per Environmental Noise Monitoring Program & Complaint Procedure (Aercoustics, Feb. 24/13).				
F47 Natural Environment Report	✓		Installation of butternut tree protection fencing at south setback, West Parcel, by a qualified ecologist prior to berm construction: not required at this time. Planting of conifer trees at edge of forested areas that are to be retained (i.e. in excavation setback or non-extraction area) has been completed.				
F48 Archaeological Assessment and Ministry of Tourism, Culture and Sport comments	✓		Buffer zone demarcation: Archaeological sites are demarcated and have not been impacted by pit operations. Markers at limit of extraction prior to extraction activities: extraction limits adjacent to the archaeological sites will be demarcated prior to aggregate extraction occurring adjacent to the sites. Worker training program: instruction has been provided to workers.				
F49 Visual Impact Assessment	✓		Input from adjacent residents on berm construction: Discussions have occurred with one homeowner and attempts made to contact the other homeowner. Variations in berm height / slope / orientation subject to noise mitigation requirements: Constructed berm has been built with a horizontal curve and final shaping will include rounding of berm. Tree/shrub planting plan with input from adjacent residents: Planting has taken place with input from McNichol. Other resident (Ferguson 'Estate') did not respond.				
General Comments:			•				
ARA Licence issued / dated January 30, 2014.							-,
S. Eddino issued / dated dalidary 50, 2014.							

Form #591 (Rev. 04/03)

THIS SECTION MUST BE COMPLETED WHEN REMEDIAL ACTION IS REQUIRED								
OPERATING STANDARDS from Pg. 1 (e.g. B4 – Fencing)	Remedial Action Required	Deadline Date	MNR Direction (for MNR use only)					
EXAMPLE B4 - Fencing	200 ft of West boundary to be fenced	June 15 / 99						
SEE NOTES BELOW REGARDING REMEDIAL ACTION DEADLINE DATES								
	· · · · · · · · · · · · · · · · · · ·							
								
			·					
Sketch Included? (see note below) Licence ID #: 624984 Codrington Pit Additional Detailed Information Attached								

Form #591 (Rev. 04/03) Page 3

[•] You must provide a sketch if remedial action is required or progressive rehabilitation has been performed.

[•] In order to extend the 90-day remedial action deadline date, you <u>must</u> obtain the Aggregate Inspector's approval (in writing) <u>prior to filing the report</u> with the Inspector or local MNR office.

Date Submitted to Y / M / D	MNR: 2015 / 0	19/29	Please ensure that the site plan you have is the most current, approved plan and is the same as the one MNR has on file.						
Is the site held in reserve? ☐ YES or ☑ NO									
Copies o	of Report Sent to:	County/l	Regional Municipality	Local Municipality	Ministry of Natural Resources				
(by Se	eptember 30th)		☑ YES	☑ _{YES}	☑ YES				
TO BE COMPLETED BY PERSON CONDUCTING REVIEW (including on-site inspection)									
Date Inspected: Y/M/D	2015 / 08 / 19	Review Conducted by: (Please Print) Amarjit S. Sandhu Signature (if repeat than licensee):							
Name of Company and Address: Pro-Inspect, 10 Davey Crescent, Amherstview ON K7N 1X6 Tel. 613-384-7067									
Position with Company	r: Princip	al							
Signature of Licens	see or Authorized Of	ficial:							
•									
Mike Lebreton Lands Manager									
The state of the s									
FOR MNR OFFICE USE ONLY									
Accepted by MNR: (✓ o	ne) YES I NO I	Date Accepted: Y / M / I		MNR Signature:					
Field Audit by MNR: (✔ o	ne) YES I NO	Date Inspected:		MNR Signature:					
Follow up Notice Required? YES NO NO Licence ID#:									

- Pursuant to Subsection 57(4) of the ARA, it is an offence to furnish false information.
- You must provide a sketch if remedial action is required or progressive rehabilitation has been performed.
- In order to extend the 90-day remedial action deadline date, you <u>must</u> obtain the Aggregate Inspector's approval (in writing) <u>prior to filing the report</u> with the Inspector or local MNR office.
- Please submit this report to the local Aggregate Inspector who administers your site, or the local MNR office.

(NOTE: ALL INFORMATION IN RESPECT OF THIS REPORT IS AVAILABLE FOR PUBLIC REVIEW)

Form #591 (Rev. 04/03)

